Approved For Release 2003/04/29 CIA-RDP84-00780R000100170013-1

Bldg + Gr. 3-1

22 APR 1963

MEMCRANIZIM FOR: Assistant Deputy Director (Intelligence)

SENECT

: Fire Prevention Modification in CCR Library

Stack Agence

REFERENCE

: Memo dad 2 Apr 63 to DO/S & ADO/L come

stilest

1. I concar in the view which you expressed in paragraph 5 of the reference.

2. The Director of Security will contact the Assistant Director for Central Reference abortly in order to arrive at a solution which will obvious the most for moving the stacks.

SIGNIC H. Gates Lloyd

Deputy Ofrector (Support)

SPA-DD/S:JHP:fmf (8 Apr 63)

Distribution:

ce: Director of Security w/O of ref & atts

Director of Lagistics w/cc of ref

Appletent Ofrector for Control Reference

Orig & 1 - Adse

7 - DD/S Chrono

Y-DD/S Subject w/ccof ref (DD/S 63-1345)

SECRET

SHOUP 1
Excluded from automatic dayngrading and declassification

Approved For Release 2003/04/25: CA-RDP84-00780R000100170013-1

10/5 63-1345

3 April 1963

MEMORANDUM FOR: Deputy Director (Support)

SUBJECT:

Fire Prevention Modification in OCE Library Stack Areas

REFERENCES:

- (a) OS Memorandum to AD/CR, Subject: Same as above, dated 23 Aug. 62 (Tab.).
- (b) AD/CR Memorandum to OS, Subject: Same as above, dated 5 November 62 (Tab F).
- (c) C/LSD Memorandum to DoI, bubject: Same as above, dated 18 Feb. (Tab C).
- 1. A fire prevention survey conducted by the CLA Safety Office recommended certain equipment modifications and other changes in the CLA Library area (cf. Tab A). The AD/CR, in response, submitted for consideration by the Office of Security certain proposed changes in compliance with the survey recommendations (cf. Tab B). He does not agree with recommendation No. 3, i.e. to remove the top shelf from each section of shelving in the stack areas, and therefore excluded it from his proposal. Subsequently, this office received a rather peremptory memorandum from Logistics Services Division, UL, advising that subject shelves would be removed (cf. Tab C). In view of the facts cited below, it is my opinion that the removal of the shelves is neither necessary nor advisable.
- 2. Basic plans for the Library's book collection, which assume a minimum of 250,000 volumes, are predicated upon the existing shelving installation. The removal of 865 shelves, representing 40,000 volumes, would mean a severe curtailment of planned research assets.
- 3. The existing shelving installation in the CLA Library stack area was coordinated with the Office of Logistics and authorized by the consulting architect and the Building Planning Staff, who assured OCR that all safety requirements as defined in the Federal Fire Safety Regulations, were satisfied. As a result, equipment was purchased by OCR and installed prior to the move at a cost in excess of \$50,000.

h. Approved For Release 2003/04/29 CTA-RDP84-00780R000400170013-1

facilities of the federal government. The National Library of Medicine, which was occupied in 1902, has a fire detection system and only six (6) inches between the top of the shelving and the ceiling. The State Department Library, which was occupied in 1961, has no fire detection system and shelving that is only one half (2) an inch from the ceiling. In the National Agricultural Library, a much older building without a fire detection system, there is no space whatsoever between the shelves and the ceiling.

5. While recognizing the need for precautionary measures, I cannot agree with the Logistics Services Division memorandum and hold with the AD/CR that no changes should be made in the shelving installation.

Assistant Deputy Director (Intelligence)

Attachments

ODDI/GSF/vcl
Distribution:
O&l-addressee
2-DDI
2-GSF
1-OCR

APR 5 9 14 AH '63

0-0012

UNCLASSIFIED Approved Harekalease 2003/04/29: CIA-RDP84-00780R000100170013-1 SECRET					
ROUTING AND RECORD SHEET					
SUBJECT: (Optional)					
Fire Prevention Modification in CCR Library Stack Areas EXTENSION NO.					
FROM	:			EXTENSION	NO.
Deputy Director (Support)					DATE 22 APR 1963
TO: (Officer designation, room number, and building)		DATE		OFFICER'S	COMMENTS (Number each comment to show from whom
1.		RECEIVED	FORWARDED	INITIALS	to whom. Draw a line across column after each comment.)
1.	Director of Security				
2.	4260 Hqs.				Shef:
					Please have your Safety Officer get
3.					in touch with CCR and work out some arrangement which will keep the
4.					stacks where they are now we just do not have the space.
5.					15/kgl
J.					for I.KW
6.					Att: Memo dtd Apr 63 to A/DD/I fr DD/S, subj; Fire Prevention
7.					Modification in CCR Library Stack Areas
8.					SPA-DD/S:JHP:fmf (8 Apr 63) Distribution:
9.					Orig - Adse w/att DD/S 63-1391 & ref w/atts 1 - DD/S Chrono
10.					DD/S Subject w/cc of att
11.					
12.					
13.					
14.					
15.					
ORM 3-62	610 USE PREVIOUS SECRET		CONFIDE	NTIAL	INTERNAL UNCLASSIFIED

STATINTL Approved For Release 2003/04/29 : CIA-RDP84-00780R000100170013-1

Approved For Release 2003/04/29 : CIA-RDP84-00780R000100170013-1